

## STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940 RECLIVED
FEB 14 2000

DIVISION OF OIL, GAS AND MINING

## ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	<u>General</u>	al Information			
	1.	Report Time Period: From (mo./yr.)1/99 To (mo./yr.)12/99			
	2.	DOGM File Number (Mine No): M / 045/037			
	3.	Mine Name: MORTON SALT / GRANTSVILLE			
	4.	Mineral(s) Mined (or permitted to mine): SALT (SODIUM CHLORIDE)			
	5.	Type of mine  ☐ Surface Mine or ☐ Underground Mine			
	6.	Legal Description (Location of Lands Affected):			
		1/4,1/4,1/4, Section, Township, Range			
		1/4,1/4,1/4, Section, Township, Range			
		1/4,1/4,1/4, Section, Township, Range			
7.	Name	Name of Operator or Company: ROHM & HAAS, MORTON SALT			
	8.	Permanent Street Address: I-80 WEST EXIT 84			
		City, State, Zip: GRANTSVILLE, UTAH 84029			
		Phone: 801-250-6335 Fax: 801-933-4410			
	9. Company Representative (or designated operator):  Name:JAMES H. HUIZINGH				
		Title: FACILITY MANAGER			
		Business Address: I-80 WEST EXIT 84 (P.O. BOX 506)			
		City, State, Zip: GRANTSVILLE, UTAH 84029			
		Phone: 801-250-6335 Fax: 801-933-4410			
		Please check if any of the above information has changed since previous year.			
II.	Mining and Reclamation				
	1.	Was there any mine related activity during the past year? Yes ₺ No □			
	2.	If no - what was the last year of activity?			
	3.	If yes - how much ore or mineral was mined? 575,152			

4.	Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.  REPAIR AND MAINTENANCE OF EXISTING DYKES			
5.	How much additional acreage was d	isturbed during the past year?	0	
6.	.  How much acreage was reclaimed du		0	
7.	Briefly describe the reclamation work	eclamation work performed during the past year. This description ds employed, and an evaluation of the results.		
8. 9.	What is the <u>total</u> disturbed acreage of entire project at years end?			
NOTE:	Section III., "Additional Information"	applies only to large mining op	erations.	
III. Additional	<u>Information</u>			
1.	An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.			
<ol> <li>Any monitoring results or other reports that are required under the terms of the approintention should also be attached.</li> </ol>				
IV. <u>Signature</u>	<u>Requirement</u>			
I here	by certify that the foregoing is tru	e and correct.		
	Name (Typed or Print):	JAMES H. HUIZINGH		
	Title of Operator:	FACILITY MANAGER		
	Signature of Operator:	James Hafring	£	
jb a:\forms\MR-AR	Date:	1-2/1/00		

- 2 -